

Primary Menu	Menu Item	Factory Setting	Function / Notes
	Out 1	0n0f	<b>Press Enter After Making Any Change</b>
	SP1d	-10	
	Out 2	0n0f	
	SP2d	-20	
	ArUP	Off	
	ArtE	Off	
	Fint	0	
	Fbnd	0	
	Fрте	0.00	
	PEA	Highest recorded temp	
	VAL	Lowest recorded temp	
	Pct0	Off	
	InPC	0	
	Filt	2	
	LPbr	Off	
Secondary Menu	Menu Item	Factory Setting	Function / Notes
	SECr	4	
	InP	J-IC	
	Unit	F	
	dPt	0	
	InPt	Off	
	SEnC	Off	
	SCAL	-100	
	SCAH	1600	
	SPL	-100	
	SPH	1600	
	SP10	OutA	
	SiSt	re	
	S1rE	0n0f	
	S1Pi	Off	

<b>Primary Menu</b>	<b>Menu Item</b>	<b>Factory Setting</b>	<b>Function / Notes</b>
	S1iH	Off	
	S1LP	0 on	
	S2t	de	
	S2St	re	
	S2re	0n0f	
	S2Pi	Off	
	S2iH	Off	
	S2LP	0on	
	AL1	Off	